

M100

TIMING POINTERS DISCONTINUED

PRODUCT AFFECTED

Model 100 Fuel Injection pumps.

INSTRUCTIONS

Timing Pointers PO 857 and PO 403718 have been discontinued. However, PO 404679 (PO 856) can be utilized to meet service requirements.

<u>P/N</u>	<u>LENGTH</u>
PO 857	- 1.000"
PO 403718	- 1.135"
PO 404679	- 1.285"

Cut off blunt end of PO 404679 as required and bevel to facilitate pin installation. Install pin in housing as required.