



ENGINE GOVERNING SYSTEMS

SERVICE BULLETIN

Section EG 110-3

SUBJECT

All Cummins KT(A) - 2300, KTA - 3067 Series Engine Applications

PRODUCTS AFFECTED

CU 673C-23, LSP 672A (containing CU 673C-17 Speed Control Unit)

REASON FOR BULLETIN

Installation utilizing the above referenced electric governor products should apply a jumper wiring connection between the speed control unit terminals H and M.

This jumper connection is needed to provide added governing stability to Cummins engines identified above.